

September 26, 1995

Description along fenceline in the Ni2 NW1/4 of Section 11, T12N, R6W, Town of Harmony, Vernon County, Wi.: commencing at a 3/4" iron bar at the North 1/4 Corner of said Section 11; thence S89°42'51"W 1317.74' to a 3/4" iron bar at the northwest corner of the NE1/4 NW1/4, the point of beginning of said line. Thence S46°45'55"W 333.91' to a 3/4" iron bar; thence S12°13'03"W 296.75' to a 3/4" iron bar; thence N81°07'40"E 533.78' to a 3/4" iron bar; thence S80°55'20"E 443.15' to a 3/4" iron bar; thence S06°00'41"E 72.59' to a 3/4" iron bar; thence continuing along said fenceline, and fenceline extended, S06°00'41"E 44.60' to the centerline of Fauske Lane, and there terminating.

(conveying: the N1/2 NW1/4 lying southerly and westerly of the above described line and westerly of Fauske Lane; the S1/2 NW1/4 lying westerly of Fauske Lane and Northerly of Johnson Lane)

SURVEYOR'S CERTIFICATE

I, F. Curtis Crook, Registered Land Surveyor, hereby certify that I have complied with State laws while conducting this survey, and that this survey map and description is a correct and true representation thereof, to the best of my knowledge and belief.

F. Curtis Crook 9-27-95

F. Curtis Crook R.L.S. 1292

WISCONSIN E. CURTIS CROOK S-1292 READSTOWN WIS. LAND SURVEYOR

survey for
Donald and Siri Halvorson to Steinman
Part NW1/4 of
Sect 11 T12N R6W
Town of Harmony,
Vernon County, Wi.

C611HALV